

Software Update KSEP 7.1



TÜV SÜD Schweiz AG (Production and Distribution)

Mattenstrasse 24, CH-4058 Basel, Switzerland

www.tuvsud.com products.bs@tuvsud.com

Cesana AG (Development and Software)

Baiergasse 56, CH-4126 Bettingen, Switzerland


www.cesana-ag.ch info@cesana-ag.ch

End of 2016, Adolf Kühner AG has ceased the production, sales and service of the Safety Testing Equipment. These products will be continued by Cesana AG and TÜV SÜD Schweiz AG. As such, the responsibility for this well-established series of instruments has been handed over to those persons and institutions that played crucial roles during the development of these devices and respective test methods.


TÜV SÜD Schweiz AG will be responsible for production and distribution of these instruments as well as providing training and support whilst Cesana AG will be responsible for software, technical development and organization of the traditional calibration round robin tests CaRo.

The KSEP software has been improved and we recommend the free update:

- a) Your computer is connected with the Internet:
Open the KSEP-Program and start the update.
(The KSEP-user needs administrator or service rights)



- b) Your computer is **not** connected with the Internet:
Copy the attached files in the KSEP-folder and
overwrite the old files.



For further support please send an e-mail to info@cesana-ag.ch